6 July 1996

MEDISTANDIM FOR: Project Director

THEFT

: Director of Operations

SUBJECT

: Wire Recorder for U-2 Pilots

- 1. Recent missions, when the camera system has malfunctioned during the flight, have quite naturally motivated the U-2 pilots to record intelligence they acquire visually. When the aircraft is traversing condensed target areas, it is obvious that considerable intelligence is lost one to the limitations of the pilots to record all they see of interest.
- 2. It appears that a light weight self-contained wire recorder would be useful to assist the U-2 pilots record items of interest. Such a recorder is evallable and is made in Germany by the "MINIFOR" Company. The device is called the MINIPON and is capable of recording 25 hours without a change of speaks. It weighs about two pounds and contains its own power supply. They may be purchased in Wiesbeden for approximately \$150.00 complete.
 - 3. It is recommended that:
 - a. A recording system be considered for the U-2 pilots.
 - b. The "MINIFOR" be investigated to determine if this device is feasible for use during our missions.

Departy serector or Operations

25X1

25X1

PCS/BCI/O/PEG/efte

Distribution:

Orig-Mitrespee

Cy 2-Ope Subj.

Cy 3-Ope chrono

Cy 4-Admin chrono

TERES 001081030



- c. It requires occasional monitoring by the pilot in flight.
- 4. It is my understanding that the Air Force has ten of these systems for test at WADC. If so, then it may be possible to acquire a few for tests with the U-2 aircraft to determine if such a system is feasible to be used for our purposes.
 - 5. It is recommended that:
 - a. This system be investigated to determine if it can be used advantageously with the U-2 sircraft.
 - b. WARC be queried to determine if they have some systems that can be used for testing.
 - c. Tests be conducted by Col. McConnell's detachment.
 - d. Should these systems not be available at WARC, we procure two (2) from Bendix or Hycon, the contractors presently building that system for the Canadians.
- 6. The systems displayed within the attached brochure was developed over two years ago. It is my understanding that considerable improvement has been made in the system represented.

25X1

Deputy Director of Operations

Attach: Brockure on Position & Homing Indicator M. 2 Photographs PCS/DCI/O/PMS/efm

Distribution: Orig-Addressoe Cy 2-Ops Subj. Cy 3-Ops chrono Cy 4-Admin chrono

013:000

80 KN (80 200)